

Handle Via
Talent-Keyhole
Control System Only

Approved For Release 2002/05/07 : CIA-RDP78T00709A008300010102-3
TOP SECRET CRESS RUFF
TCS-20119/68
FEBRUARY 1968

NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

NOTICE TO RECIPIENTS OF TCS-20069/68



25X1D

MIDDLE EAST AND AFRICA

1. IN THE HIGHLIGHTS, PAGE 5, UNDER CONSTRUCTION STATUS OF 3 MAJOR AIRFIELDS IN SYRIA, CHANGE THE HEADING AND INFORMATION TO THE FOLLOWING:

CONSTRUCTION STATUS OF 4 MAJOR AIRFIELDS IN SYRIA


CONSTRUCTION CONTINUES ON MARJ RHAYAL AIRFIELD AND THE 9,000-FT RUNWAY IS BEING SURFACED. CONSTRUCTION IS PROGRESSING AT A SLOW RATE AT JAYRUD AND DAMASCUS EAST AIRFIELDS AND APPEARS SUSPENDED AT KHALKHALAH AIRFIELD. THE 9,000-FT GRADED-EARTH RUNWAY AT JAYRUD AIRFIELD APPEARS UNSERVICEABLE AND THE 8,860-FT RUNWAY AT DAMASCUS EAST AIRFIELD APPEARS TO BE POSSIBLY SERVICEABLE. NO AIRCRAFT ARE OBSERVED AT THE 4 AIRFIELDS.

2. ON PAGE 23, SUBSTITUTE THE FOLLOWING READOUT FOR KHALKHALAH AIRFIELD (NO COMIREX):

OB -- NONE OBSERVED.

CONSTRUCTION APPEARS TO BE SUSPENDED AND THE 10,000 X 340-FT NNW/SSE RUNWAY REMAINS UNSERVICEABLE.

25X1D



3. ADD THE FOLLOWING TARGET:


MARJ RHAYAL AIRFIELD SY 3317//N 03627//E
[Redacted] NO COMRX

25X1A

OB --- NONE OBSERVED.

THE 9,000 X 100-FT NE/SW RUNWAY IS BEING SURFACED WITH CONCRETE AND IS UNSERVICEABLE. AT LEAST 4 NEW HANGARETTES ARE OBSERVED AT THE SW END OF THE RUNWAY FOR A NEW TOTAL OF 12 HANGARETTES.

25X1D



Declass Review by NIMA/DOD

TOP SECRET

TAS-20069/68

CONTROL NO. _____ TCS-20119/68

Copy 203

REFERRED TO OFFICE	RECEIVED			RELEASED		SEEN BY	
	SIGNATURE	DATE	TIME	DATE	TIME	NAME & OFFICE SYMBOL	DATE

Handle Via Indicated Controls

TALENT-KEYHOLE

.....

.....

.....

.....

WARNING

This document contains information affecting the national security of the United States within the meaning of the espionage laws U. S. Code Title 18, Sections 793 and 794. The law prohibits its transmission or the revelation of its contents in any manner to an unauthorized person, as well as its use in any manner prejudicial to the safety or interest of the United States or for the benefit of any foreign government to the detriment of the United States. It is to be seen only by personnel especially indoctrinated and authorized to receive information in the designated control channels. Its security must be maintained in accordance with regulations pertaining to TALENT-KEYHOLE Control System.

TOP SECRET